## **EAST Search History**

Ref#	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	28	("20020027154"   "20020079351"   "20030000624"   "20030000996"   "20030000997"   "20030192941"   "20040055349"   "20040074949"   "20040195293"   "20040197159"   "20050011933"   "5400633"   "5971252"   "6053391"   "6185977"   "6209379"   "6315187"   "6471112"   "6543671"   "6572007"   "6772007"   "6777107"   "6857555"   "6273323"   "6655575"   "6712916"   "6726085").PN.	US-PGPUB; USPAT	OR	ON	2008/03/09 09:09
S2	944	((friction near5 (agitat \$4 or plug\$4 or plung \$4 or stir\$4)) near5 (insert\$3 or patch\$3 or repair\$3 or segment or (cut adj out)))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/09 09:16
S3	61	S2 and (superplastic \$4 or ((hydro or air or blow or liquid or water or pneumatic or diffusion) near5 form \$3))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/09 09:21
S4	984	(228/112.1,2.1).ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/09 09:27

S5	62	S4 and (weld\$3 and (superplastic\$4 or ((hydro or air or blow or liquid or water or pneumatic or diffusion) near5 form\$3)))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/09 09:27
S6	49	S5 and (insert\$3 or patch\$3 or repair\$3 or segment or (cut adj out))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/09 09:31
S7	17	("4351470"   "5204161"   "5224645"   "5687900"   "5797239"   "5881459"   "5994666"   "6053391"   "6138898"   "6337471"   "6378264").PN. OR ("6568582").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/03/09 09:35
S8	98	((preform or blank) near5 weld\$3 near5 (insert or patch or (cut adj out)))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/09 09:44
S9	14	(parent near5 weld\$3 near5 (insert or patch or (cut adj out)))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/09 09:49
S10	143	S2 and Plasticiz\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/09 09:52

## 3/10/2008 1:03:38 PM

C:\Documents and Settings\maboagye\My Documents\EAST\Workspaces\10552189 method of forming a blank Faom 228-112.1 03-09-2008.wsp